



VENTA MÆRSK  
KØBENHAVN

IMO 9775763

Pilot Transfer Arrangements -  
Are they getting any safer?
















Both ropes broke when the pilot was climbing down and the pilot fell onto the boat deck with the ladder.





# Looking at the rear window?

- Safety of pilot transfer arrangements seems to be deteriorating - not improving.
- PTA are not considered properly in new buildings.
- Finnish PSC Authority Traficom has been supporting us strongly and further discussions will be held.
- Finnpilot added PTA to service conditions in 2018:
  - Poor arrangements - NO pilot
- Campaign for enhanced checking of PTA
- Would you like to join us?



FINNPILOT





THANK YOU!



FINNPILOT



